



PRAISTON Sp. z o.o.
ul. Górowska 32
64-100 Leszno
Polska

Biuro: +48 65 527 01 67
Serwis: +48 782 844 000
Fax: +48 65 527 01 67

E-mail: biuro@praiston.pl

Koordynator ds. sprzedaży
Krzysztof Wybieralski
+48 882 762 006

kw@praiston.pl



Philips - HP SpO2 Sensor (New)

- New,
- Made in Uruguay,
- Options:
 - Adult Clip,
 - Adult Silicone,
 - Pediatric Clip,
 - Pediatric Silicone,
 - Neonate/Multisite,
 - Wrap Silicone,
- **Cable Length 2,7 m** (cable extension available on demand),
- Compatible with:
 - 78352A, 78352C, 78354A, 78354C, 78834C, M1020A, M1025A, M1025B, M1092A, M1094B, M1204A, M1205A, M1350B, M1722A, M1722B, M1190A, M1723A, M1723B, M1732A, M1732B, M2475B, M3046A M4, V24E, Codemaster, HeartStart XL, Agilent 50XM Fetal Monitor,
 - C1, C3, M3, M4, MP20, MP30, MP40, MP50, MP60, MP70, MP80, MP90, VM4, VM6, VM8, HP Viridia 24C, Philips HeartStart defibrillator and IntelliVue,
 - Goldway G40,
 - Solaris NT2A, NT2C,
 - MP20, MP30, MP40, MP50, MP60, MP70, MP90, VN4, VN6, VN8 with M. Tech,
- **Cable Length 0,9m** (cable extension available on demand),
- Compatible with:
 - Viridia 24C, C1, C3, M3, M4, MP20, MP30, MP40, MP50, MP60, MP70, MP80, MP90, VM4, VM6, VM8, HeartStart MRx and SureSigns VS3,
 - 78352A, 78352C, 78354A, 78354C, 78834C, M1020A, M1025A, M1025B, M1092A, M1094B, M1204A, M1205A, M1350B, M1722A, M1722B, M1190A, M1723A, M1723B, M1732A, M1732B, M2475B, M3046A M4, V24E, Codemaster, HeartStart XL, Agilent 50XM Fetal Monitor, C1, C3, M3, M4, MP20, MP30, MP40, MP50, MP60, MP70, MP80, MP90, VM4, VM6, VM8, HP Viridia 24C, Philips HeartStart defibrillator and IntelliVue;
- 12 months warranty

