



**PRAISTON Sp. z o.o.**  
ul. Górowska 32  
64-100 Leszno  
Polska

Biuro: +48 65 527 01 67  
Serwis: +48 782 844 000  
Fax: +48 65 527 01 67

E-mail: [biuro@praiston.pl](mailto:biuro@praiston.pl)

Koordynator ds. sprzedaży  
Krzysztof Wybieralski  
+48 882 762 006

[kw@praiston.pl](mailto:kw@praiston.pl)



**Philips HP ECG Cable (New)**

- New,
- Made in Uruguay,
- Code: IEC
- Options:
  - **Cable Length: 3,5 m**
    - 3 leads snap (BIOECG.HP1.S3F),
    - 3 leads clamp (BIOECG.HP1.C3F),
    - 5 leads snap (BIOECG.HP1.S5F),
    - 5 leads clamp (BIOECG.HP1.C5F),
  - **Compatible with:**
    - Codemaster XL, Codemaster 100, 43100A, 43110A, 43110M, 43120A, MC Defibrillator, 43200A Portable, M3500B, 77000AC, 77020A, 77010AC, Sonos/AC/AR, 77025A, 77030A, 77035A, 77040A, 78208A, 78210A, 78330A, 7833 1A, 78332A, 78333A, 78341A, 78342A, 78345A, 78346A, 78351T, 78352A/C, 78353A/B, 78354A, 78532A/B, 78534A/B/C, 78619A, 78620A, 78660A/B, 78661A/B, 78670A, 78671A, M1722A/B, M1723A/B, M2400A, M2406A, Sonos 2000/2500, tems, M2425A, M2475B,
  - **Cable Length: 4,0 m**
    - 3 leads snap (BIOECG.HP1.S3D),
    - 3 leads clamp (BIOECG.HP1.C3D),
    - 5 leads snap (BIOECG.HP1.S5D),
    - 5 leads clamp (BIOECG.HP1.C5D),
  - **Compatible with:**
    - Codemaster XL, Codemaster 100, 43100A, 43110A, 43110M, 43120A, MC Defibrillator, 43200A Portable, M3500B, 77000AC, 77020A, 77010AC, Sonos/AC/AR, 77025A, 77030A, 77035A, 77040A, 78208A, 78210A, 78330A, 7833 1A, 78332A, 78333A, 78341A, 78342A, 78345A, 78346A, 78351T, 78352A/C, 78353A/B, 78354A, 78532A/B, 78534A/B/C, 78619A, 78620A, 78660A/B, 78661A/B, 78670A, 78671A, M1722A/B, M1723A/B, M2400A, M2406A, Sonos 2000/2500, tems, M2425A, M2475B
  - **Cable Length: 3,0 m (this product requires a lead set)**
    - 3 leads (BIOECG.HP1.3T),
    - 5 leads (BIOECG.HP1.5T),
  - **Compatible with:**
    - Codemaster XL, Codemaster 100, 43100A, 43110A, 43110M, 43120A, MC Defibrillator, 43200A Portable, M3500B, 77000AC, 77020A, 77010AC, Sonos/AC/AR, 77025A, 77030A, 77035A, 77040A, 78208A, 78210A, 78330A, 7833 1A, 78332A, 78333A, 78341A, 78342A, 78345A, 78346A, 78351T, 78352A/C, 78353A/B, 78354A, 78532A/B, 78534A/B/C, 78619A, 78620A, 78660A/B, 78661A/B, 78670A, 78671A, M1722A/B, M1723A/B, M2400A, M2406A, Sonos 2000/2500, tems, M2425A, M2475B
  - **Cable Length: 1,0 m (this product requires a trunk cable)**
    - 3 leads snap (BIOECG.RA.S3),
    - 3 leads clamp (BIOECG.RA.C3),
    - 5 leads snap (BIOECG.RA.S5),
    - 5 leads clamp (BIOECG.RA.C5),
  - **Compatible with:**
    - Codemaster XL, Codemaster 100, 43100A, 43110A, 43110M, 43120A, MC Defibrillator, 43200A Portable, M3500B, 77000AC, 77020A, 77010AC, Sonos/AC/AR, 77025A, 77030A, 77035A, 77040A, 78208A, 78210A, 78330A, 7833 1A, 78332A, 78333A, 78341A, 78342A, 78345A, 78346A, 78351T, 78352A/C, 78353A/B, 78354A, 78532A/B, 78534A/B/C, 78619A, 78620A, 78660A/B, 78661A/B, 78670A, 78671A, M1722A/B, M1723A/B, M2400A, M2406A, Sonos 2000/2500, tems, M2425A, M2475B,
  - **Cable Length: 3,5 m**
    - 3 leads snap (BIOECG.HP2.S3F),
    - 3 leads clamp (BIOECG.HP2.C3F),
    - 5 leads snap (BIOECG.HP2.S5F),
    - 5 leads clamp (BIOECG.HP2.C5F),
  - **Compatible with:**
    - Merlin, Viridia, Omnicare CMA, Heartstream, Codemaster XL, odemaster 100, Philips Heartstart desfibrilator, Philips Agilent, Envisor, IntelliVue, MP-20, MP-30, MP-50, IE33, 43100A, 43110A, 43120A, 78352C, 78354C, 78834C, 862474-C3, M1001A/B, M1002A/B, M3002A, MMS X2, M8102A MP2, M8105A MP5, M1165A, M1166A, M1167A, M1175A, M1177A, M1204A, M1205A, M1264A, M1275A Transport, M1280A, M1722A/B, M1723A/B, M2400A, M2406A, M2601A, M3000A, M3001A, M3046A, M2, M3, M4, M4735A, V24E, Agilent 50XM Fetal Monitor, Newtech NT3A, 862472, 862473, 862474, 862475, 862478, 862479, 863064, 863065, 863066, 863068, VM6, VM8, M4735A, HeartStart XL, M3535A, M3536A, Solaris NT3A, NT3B, NT3C, NT3E, NT3F,
  - **Cable Length: 4,0 m**
    - 3 leads snap (BIOECG.HP2.S3D),
    - 3 leads clamp (BIOECG.HP2.C3D),
    - 5 leads snap (BIOECG.HP2.S5D),
    - 5 leads clamp (BIOECG.HP2.C5D),
  - **Compatible with:**
    - Merlin, Viridia, Omnicare CMA, Heartstream, Codemaster XL, Codemaster 100, Philips Heartstart desfibrilator, Philips Agilent, Envisor, IntelliVue, MP-20, MP-30, MP-50, IE33, 43100A, 43110A, 43120A, 78352C, 78354C, 78834C, 862474-C3, M1001A/B, M1002A/B, M3002A, MMS X2, M8102A MP2, M8105A MP5, M1165A, M1166A, M1167A, M1175A, M1177A, M1204A, M1205A, M1264A, M1275A Transport, M1280A, M1722A/B, M1723A/B, M2400A, M2406A, M2601A, M3000A, M3001A, M3046A, M2, M3, M4, M4735A, V24E, Agilent 50XM Fetal Monitor, Newtech NT3A, 862472, 862473, 862474, 862475, 862478, 862479, 863064, 863065, 863066, 863068, VM6, VM8, M4735A, HeartStart XL, M3535A, M3536A, Solaris NT3A, NT3B, NT3C, NT3E, NT3F
  - **Cable Length: 3,0 m (this product requires a lead set)**
    - 3 leads (BIOECG.HP2.3T),
    - 5 leads (BIOECG.HP2.5T),
  - **Compatible with :**
    - Merlin, Viridia, Omnicare CMA, Heartstream, Codemaster XL, Codemaster 100, Philips Heartstart desfibrilator, Philips Agilent, Envisor, IntelliVue, MP-20, MP-30, MP-50, IE33, 43100A, 43110A, 43120A, 78352C, 78354C, 78834C, 862474-C3, M1001A/B, M1002A/B, M3002A, MMS X2, M8102A MP2, M8105A MP5, M1165A, M1166A, M1167A, M1175A, M1177A, M1204A, M1205A, M1264A, M1275A Transport, M1280A, M1722A/B, M1723A/B, M2400A, M2406A, M2601A, M3000A, M3001A, M3046A, M2, M3, M4, M4735A, V24E, Agilent 50XM Fetal Monitor, Newtech NT3A, 862472, 862473, 862474, 862475, 862478, 862479, 863064, 863065, 863066, 863068, VM6, VM8, M4735A, HeartStart XL, M3535A, M3536A, Solaris NT3A, NT3B, NT3C, NT3E, NT3F,
  - **Cable Length: 1,0 m (this product requires a trunk cable)**
    - 3 leads snap (BIOECG.RA.S3),
    - 3 leads clamp (BIOECG.RA.C3),
    - 5 leads snap (BIOECG.RA.S5),
    - 5 leads clamp (BIOECG.RA.C5),
  - **Compatible with:**
    - Merlin, Viridia, Omnicare CMA, Heartstream, Codemaster XL, Codemaster 100, Philips Heartstart desfibrilator, Philips Agilent, Envisor, IntelliVue, MP-20, MP-30, MP-50, IE33, 43100A, 43110A, 43120A, 78352C, 78354C, 78834C, 862474-C3, M1001A/B, M1002A/B, M3002A, MMS X2, M8102A MP2, M8105A MP5, M1165A, M1166A, M1167A, M1175A, M1177A, M1204A, M1205A, M1264A, M1275A Transport, M1280A, M1722A/B, M1723A/B, M2400A, M2406A, M2601A, M3000A, M3001A, M3046A, M2, M3, M4, M4735A, V24E, Agilent 50XM Fetal Monitor, Newtech NT3A, 862472, 862473, 862474, 862475, 862478, 862479, 863064, 863065, 863066, 863068, VM6, VM8, M4735A, HeartStart XL, M3535A, M3536A, Solaris NT3A, NT3B, NT3C, NT3E, NT3F
  - **Cable Length: 3,0**
    - 10 lead banana 4 mm (BIOECG.HP.P10F),
  - **Compatible with:**
    - M1770A, M1771A, M1772A, PageWriter 100, 200, 200i and Agilent 300i, 300PI; CardioTech CRT-6U, CRT-6D, CRT-6T; Bionet Cardiocare 2000; Delmar Raynolds CardioCollect 12; BLT-08 LT ECG; Spacelabs CardioDirect 12; Woodway Cortex CPX System; Welch Allyn CP 100 and CP 200
- **Cable extension available on demand,**
- 12 months warranty



| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |

| Philips - HP | System | Code        |
|--------------|--------|-------------|
| HP-1000-001  | System | HP-1000-001 |
| HP-1000-002  | System | HP-1000-002 |
| HP-1000-003  | System | HP-1000-003 |
| HP-1000-004  | System | HP-1000-004 |